

:+79021555781
 , 11
 WWW: E- mail:sisert.toris@gmail.com

ScanTronik II
 ID
 Sc150311- 16
 www.scantronic.ucoz.ru

Report List 5 24.8.2013

()

:	Mitsubishi	:	LANCER	:	2006
.	A363AK 96	VIN:	JMBSNCS3A6U018146	:	130189
:	. .			:	

Connector selection
 Select [Mitsubishi 12+16PIN] connector.

SYSTEM ID
 System ID: E24F

1. Error 12:46 24.8.2013

P0340	Camshaft position sensor	P0340
-------	--------------------------	-------

!

SYSTEM ID
 System ID: 7195

2. Error 12:47 24.8.2013

22	D- AB SQ TRBL2	
----	----------------	--

!

?

```

:                                     ->                               : Mitsubishi\ Ver. Program 2.8 (R270311) ru -> SELECT M
ENU:FROM 2006 -> SELECT MENU:Europe -> SELECT MENU:LANCER(CS#,CT#) -> SELECT MENU:2006 -> SELECT MENU:CS3A
-> SELECT MENU:SNJEL6 -> SYSTEM SEL.:MPI/ GDI/ DIESEL ->                                     :                               -> TROUBLE
CODES:BACK ->                                     :                               ->                               -> SELECT DATA ITE
M:BACK ->                                     :BACK -> SYSTEM SEL.:SRS- Air Bag ->                                     :                               ->
TROUBLE CODES:BACK ->                                     :                               ->                               -> DATA S
TREAM:CANCEL ->                                     :BACK -> SYSTEM SEL.:BACK -> SELECT MENU:BACK -> SELECT MENU:BACK ->
SELECT MENU:BACK -> SELECT MENU:BACK -> SELECT MENU:BACK -> SELECT MENU:BACK ->
  
```

:

: _____ :